

PRODUCT SAFETY RECALL
STRIKE FIRST CORPORATION OF AMERICA
NOTICE TO OWNER

TO: OWNERS OF CERTAIN STRIKE FIRST FIRE EXTINGUISHERS

SUBJECT: Strike First 2.5 lb and 5 lb Dry Chemical Fire Extinguishers

- Models WBSF-ABC110AP, WBSF-ABC210AP and WBSF-ABC340AP
- Certain serial numbers only (see below)

DATE: December 2005

Strike First retrofit program

Strike First Corporation of America (“Strike First”) has determined that the valve stem seat in a number of its 2.5 and 5 lb Strike First dry chemical fire extinguishers is oversized. The oversized part prevents some of the affected fire extinguishers from discharging their contents at the proper velocity, or at all, when the lever is activated. As a result of this condition, Strike First has initiated a fire extinguisher retrofit program for potentially affected units.

How does the retrofit program work?

Strike First is making available to qualified fire extinguisher service organizations, free of charge, retrofit kits for retrofitting the fire extinguishers that are affected by this Notice. If you currently possess fire extinguishers that fall within the range of serial numbers affected by this Notice, Strike First asks that you immediately contact your fire extinguisher service company to request that the affected units be retrofitted. Once the valve stem assembly in an affected unit is properly replaced by a qualified fire extinguisher service organization, the unit will discharge as intended.

How to identify affected units

Only Strike First models WBSF-ABC110AP, WBSF-ABC210AP and WBSF-ABC340AP with the following serial numbers are subject to this Notice.

<u>Model number</u>	<u>Affected serial numbers</u>
WBSF-ABC110AP	TC101566-TC108819
WBSF-ABC210AP	TC114969-TC135000 VV822001-VV832000 WH161001-WH167622
WBSF-ABC340AP	TC135894-TC142345

To locate the serial number, look at the label of the fire extinguisher, below the “UL” mark, as depicted in the following photographs:

WBSF-ABC110AP



WBSF-ABC210AP



WBSF-ABC340AP



Contacting Strike First

For further information please contact Strike First directly by mail, phone, fax, email or internet at any of the following addresses: Strike First Corporation of America, 1330 Progress Drive, Front Royal, Virginia, 22630. Telephone: 1-800-255-5515. Fax: 1-800-822-5001. Email: info@strikefirstusa.com Website: www.strikefirstusa.com

Appendix 1

WBSF-ABC110AP



WBSF-ABC210AP



WBSF-ABC340AP



Appendix 2

WBSF-ABC110AP



Serial Number

Model Number

WBSF-ABC210AP



WBSF-ABC340AP

